

## HASSAN DIVISION.

*The 2nd February 1898.*

Notice is hereby given that sealed tenders will be received at the office of the Executive Engineer, Hassan division, up to 28th February 1898, for restoring Mosale Dodkere, Registered No. 702, Hassan taluk. An approximate estimate of quantities is given below. These quantities are not guaranteed. The work should be completed by the end of April 1899.

2. The plans, detailed estimate, and conditions may be seen at the Executive Engineer's office at Hassan between the hours of 11 A. M. and 5 P. M.

3. Tenders should be submitted on printed forms which may be obtained from the Executive Engineer and accompanied by a statement in the form given below, showing the rates at which the different items specified will be executed.

4. Each tender must be accompanied by a deposit of Rupees 175 in cash or Government Promissory Notes, as earnest money, and be superscribed "Tender for Restoring Mosale Dodkere, Registered No. 702, Hassan taluk," in default of which, tenders will be rejected.

5. The final acceptance of any tender will rest with the Superintending Engineer, who does not bind himself to accept the lowest or any tender or to assign any reason whatever for the rejection of any tender.

6. Within eight days of the acceptance of the tender, the successful competitor will be required to execute the usual contract bond; in default of which, his tender will be considered cancelled, and his earnest money will be forfeited.

7. The name of the successful competitor, whose tender has been accepted will be posted on the notice board in the Executive Engineer's office in due course. No enquiries regarding the acceptance or rejection of a tender will receive any reply.

8. On acceptance of one of the tenders, the earnest money on rejected tenders will be returned.

Bund—	Items of work.	Per.	Quantity.
Earthwork	.. ..	C. yd.	13,184
Do	do .. ..	Do	6,695
Old stone work with fresh jelly	.. ..	Do	1,204
New do and stones pitching	.. ..	Do	2,655
Grade stone	.. ..	No.	47
Vis a Vis stones	.. ..	Do	47
Registered No. stone	.. ..	Do	1
Gauge stones	.. ..	Do	1
B. M. stones	.. ..	Do	2
Turfing	.. ..	Sq. yds.	120.89
Sluices—	<i>Left.</i>		
Excavation	.. ..	C. yd.	21
Burnt brick in surki mortar	.. ..	C. ft.	489
Surki plastering	.. ..	Sqr.	2.20
Burnt stone slabs	.. ..	Sq. ft.	28
Raising walls of front cisterin, complete	.. ..	L. S.	..
Removing and re-fixing jibbet stone	.. ..	L. S.	..
	<i>Right.</i>		
Excavation	.. ..	C. yd.	13
Burnt brick in surki mortar	.. ..	C. ft.	441
Burnt stone slabs	.. ..	S. ft.	28
Surki plastering	.. ..	Sqr.	2.16
Waste weir, left—			
Excavation	.. ..	C. yd.	126
Burnt brick in surki mortar	.. ..	C. ft.	2,176
Rough stone work, new	.. ..	C. yd.	260
Plastering surki	.. ..	Sqr.	8.18
Burnt stone slabs	.. ..	S. ft.	488
Waste weir, right—130'			
Excavation	.. ..	C. yd.	155
Burnt brick in surki mortar	.. ..	C. ft.	1,469
Burnt stone slabs	.. ..	S. ft.	377
Plastering surki	.. ..	Sqr.	5.00
Rough stone work new	.. ..	C. yd.	207
Distribution—	<i>Channel.</i>		
Excavation sluice channel	.. ..	C. yd.	3,973
Aqueduct—			
Excavation	.. ..	C. yd.	103
Earthwork	.. ..	Do	60
Rough stone in surki mortar	.. ..	C. ft.	134
Pointing do	.. ..	Sqr.	4.7
Burnt brick in surki mortar	.. ..	C. ft.	334
Plastering	.. ..	Sqr.	2.95
Surki concrete	.. ..	C. ft.	39
Burnt stone slabs	.. ..	C. ft.	61
Rough stone work, new	.. ..	C. ft.	31
Do old	.. ..	Do	12

A. S. NAGAVKAR, Executive Engineer.